RBC ESTIMATION
DESIGN | ESTIMATION | MANAGEMENT

Email: info@rbcestimation.com

Call/WhatsApp: +1 737 307 6614

GC ESTIMATE - BASE BID SUMMARY

Project Name:	Location:	Scope of Work:	Building Type:	Levels:	Building Area:
Sample GC 01	New York	GC	Residential	2	1978 SF

CSI DIVISION	DESCRIPTION	TOTAL DIVISION COST	DIVISION COST / SQ. FT.
Division 00	Procurement and Contracting Requirements	-	-
Division 01	General Requirements	-	-
Division 02	Existing Conditions	-	-
Division 03	Concrete	-	-
Division 05	Metals	-	-
Division 06	Wood, Plastics, and Composites	-	-
Division 07	Thermal and Moisture Protection	-	-
Division 08	Openings	-	-
Division 09	Finishes	-	-
Division 10	Specialties	-	-
Division 12	Furnishings	-	-
Division 31	Earthwork	-	-
Division 32	Exterior Improvements	-	-
	SUB TOTAL	-	-
SUB TOTAL		-	-
OVERHEAD	10%	-	-
PROFIT	10%	-	-
CONTIGENCY	1%	-	-
INSURANCE	8%	-	-
LABOUR TAX	8%	-	-
SALES TAX	8%	-	-
MATERIAL MARKUP	0%	-	-
SUGGESTED BID		-	-

RBC ESTIMATION
DESIGN | ESTIMATION | MANAGEMENT

RBC ESTIMATION
DESIGN | ESTIMATION | MANAGEMENT

Email: info@rbcestimation.com

Call/WhatsApp: +1 737 307 6614

GC ESTIMATE - ALTERNATE SUMMARY

Project Name:	Location:	Scope of Work:	Building Type:	Levels:	Building Area:
Sample GC 01	New York	GC	Residential	1	980 SF

CSI DIVISION	DESCRIPTION	TOTAL DIVISION COST	DIVISION COST / SQ. FT.
Division 00	Procurement and Contracting Requirements	-	-
Division 01	General Requirements	-	-
Division 02	Existing Conditions	-	-
Division 06	Wood, Plastics, and Composites	-	-
Division 08	Openings	-	-
Division 09	Finishes	-	-
Division 10	Specialties	-	-
Division 12	Furnishings	-	-
	SUB TOTAL	-	-
SUB TOTAL		-	-
OVERHEAD	10%	-	-
PROFIT	10%	-	-
CONTIGENCY	1%	-	-
INSURANCE	8%	-	-
LABOUR TAX	8%	-	-
SALES TAX	8%	-	-
MATERIAL MARKUP	0%	-	-
SUGGESTED BID		-	-

RBC ESTIMATION
DESIGN | ESTIMATION | MANAGEMENT

Email: info@rbcestimation.com

Call/WhatsApp: +1 737 307 6614

GC ESTIMATE - BASE BID

Project Name:	Location:	Scope of Work:	Building Type:
Sample GC 01	New York	GC	Residential

#	REF.	DESCRIPTION	QTY.	UNIT	WASTAGE	TOTAL QTY.	UNIT COST	TOTAL COST
00. PROCUREMENT & CONTRACTING REQUIREMENTS								
01. GENERAL CONDITIONS								
INDIRECT PROJECT COSTS								
12		General Liability Insurance	0	Mo	0	0	-	-
13		General Conditions (Backoffice Overhead)	0	Mo	0	0	-	-
DIRECT PROJECT COSTS								
14		Bonding Fee (If required)	1.15	Mo	0	1.15	-	-
15		Access Control (Pipe Scaffolding or Boom/Scissor Lifts)	1	Mo	0	1	-	-
16		Equipment Rental	1	Mo	0	1	-	-
17		Travel, Tools, Gas	1	Mo	0	1	-	-
18		Field Office	1	Mo	0	1	-	-
19		Temp. Facilities	1	Mo	0	1	-	-
20		Temp. Signage and Protection	1	Mo	0	1	-	-
21		Temp. Fencing	1	Mo	0	1	-	-
22		Field Superintendent/Foreman (Full Time)	1	Mo	0	1	-	-
23		Project Manager (Part Time)	1	Mo	0	1	-	-
02. DEMOLITION OF EXISTING ITEMS								
REMOVAL, DEMOLITION								
24		Remove Existing Wall	370	SF	0.1	407	-	-
25		Remove Existing Baseboard	46.16	LF	0.1	51	-	-
26		Remove Existing Wall Tile	84.88	SF	0.1	94	-	-
27		Remove Existing Threshold	3.08	LF	0.1	4	-	-
28		Remove & Reinstall Crown Molding	208.39	LF	0.1	230	-	-
29		Remove & Reinstall Wall Base	17.89	LF	0.1	20	-	-
30		Remove Existing Crown Molding	142.11	LF	0.1	157	-	-
31		Remove Existing Metal Handrail	11.9	LF	0.1	14	-	-
32		Remove Existing Stone Step	1.78	SF	0.1	2	-	-
33		Remove Existing Wood Ramp	23.9	SF	0.1	27	-	-
34		Remove Existing Millwork	14.08	SF	0.1	16	-	-
35		Remove Existing Carpet & Pad	54.56	SF	0.1	61	-	-
36		Remove Existing Concrete Stair	30.29	SF	0.1	34	-	-
37		Remove Existing Ceiling Tile System W/ Fixtures	578.99	SF	0.1	637	-	-

RBC ESTIMATION
DESIGN | ESTIMATION | MANAGEMENT

Email: info@rbcestimation.com

Call/WhatsApp: +1 737 307 6614

#	REF.	DESCRIPTION	QTY.	UNIT	WASTAGE	TOTAL QTY.	UNIT COST	TOTAL COST
38		Remove Existing Gypsum Ceiling	11.84	SF	0.1	14	-	-
39		Remove Existing Bead Board Ceiling	19.83	SF	0.1	22	-	-
40		Remove Existing Plaster & Lath Ceiling	100.7	SF	0.1	111	-	-
41		Remove Grey air-cell (polyethylene cloth) asbestos pipe insulation	1	LS	0.1	2	-	-
42		Remove Existing Plumbing Fixtures	6	EA	0	6	-	-
43		Remove Existing Plumbing Vent	1	EA	0	1	-	-
44		Remove & Reinstall Existing Door	1	EA	0	1	-	-
45		Remove Existing Door	1	EA	0	1	-	-
46		Remove & Reinstall Existing Door Hardware	1	EA	0	1	-	-
47		3" Core Drill	10	EA	0	10	-	-
48		Repair And Restore Existing Wood Railing	5.66	LF	0.1	7	-	-
49		Refinish Existing Wood Stairs. Replace All Broken Treads (APX. 25%)	1	LS	0.1	2	-	-
50		Patch And Repair Existing Plaster And Lath Walls & Preparation For Paint	5710	SF	0.1	6281	-	-
51		Patch & Repair Existing Plaster & Lath Ceiling & Prepare For Paint	490.59	SF	0.1	540	-	-
52		Repair Existing Beadboard Ceiling	20.72	SF	0.1	23	-	-
03. CONCRETE								
CAST IN PLACE CONCRETE								
CONCRETE FOR FOUNDATION								
53		(2'-0"x1'-0") Concrete Footing @ Stair Reinforced W/#5 Bar @ 2' O.C. -(3)#5 Bar	1.12	CY	0.1	1.24	-	-
54		(3'-0"x1'-0") 6"Compacted Crushed Stone Sub Base	1.68	CY	0.1	1.86	-	-
CONCRETE FOR WALLS								
55		8" Concrete Wall Reinforced W/#4 @ 1' O.C.	2.25	CY	0.1	2.48	-	-
56		12" Concrete Wall Reinforced W/#4 @ 1' O.C.	1.05	CY	0.1	1.16	-	-
CONCRETE FOR STAIR								
57		6" Concrete Stair Reinforced W/ #4 Bar @ 12" E.W. & Nosing Bar	1	CY	0.1	1.1	-	-
05. METALS								
COLF FORMED METAL FRAMING								
RAILING								
58		1-1/2" x 14 GA. Painted Steel Tube Handrail 3/4" Dia. Handrail Brackets @ 4" O/C -1-1/2" x 1-1/2" Steel Guardrail Post	19.1	LF	0.1	22	-	-
59		0503 | Decorative Painted Steel Top Guardrail -1" x 1-1/2" Painted Steel Bottom Rail -1/2" x 1/2" Painted Steel Baluster @ 3" O/C	11.58	LF	0.1	13	-	-

RBC ESTIMATION
DESIGN | ESTIMATION | MANAGEMENT

Email: info@rbcestimation.com

Call/WhatsApp: +1 737 307 6614

#	REF.	DESCRIPTION	QTY.	UNIT	WASTAGE	TOTAL QTY.	UNIT COST	TOTAL COST
06. WOOD PLASTICS & COMPOSITES								
ROUGH CARPENTRY								
WOODEN TRUSS & JOISTS								
60		1x3 Wood Studs @ 12" O.C.	1114.88	LF	0.1	1227	-	-
WALL FRAMING								
61		2x3 Wood Studs @ 16" O.C.	511.28	LF	0.1	563	-	-
62		2x3 Wood T&B Plate	204	LF	0.1	225	-	-
63		2x4 Wood Studs @ 16" O.C.	421.05	LF	0.1	464	-	-
64		2x4 Wood T&B Plate	168	LF	0.1	185	-	-
BLOCKING								
65		2"x4" Wood Blocking	36	LF	0.1	40	-	-
FINISHED CARPENTRY								
MILLWORK								
66		(2'-2" Deep) Base Cabinet	5.41	LF	0.1	6	-	-
67		(2'-0" Deep) Base Vanity Cabinet	2.46	LF	0.1	3	-	-
68		3/4" Finished Wood Board	24	SF	0.1	27	-	-
07. THERMAL & MOISTURE PROTECTION								
INSULATION								
69		Weather Barrier @ Wood Decking	14.34	SF	0.1	16	-	-
70		Acoustic Insulation Batt	1240	SF	0.1	1364	-	-
ROOF ACCESSORIES								
FLASHING & SHEET METALS								
71		Custom Pre-Manufacturer Solid 20GA SS Chase Cover W/ Diagonal Creases	2	EA	0	2	-	-
72		1/2" Drip Edge	26.51	LF	0.1	30	-	-
08. OPENINGS								
DOORS & FRAMES								
DOOR								
73		(2'-6"x7'-0") Single Leaf Wood Door W/Frame	3	EA	0	3	-	-
74		(2'-5"x6'-10") Single Leaf Wood Door	1	EA	0	1	-	-
75		(3'-0"x7'-0") Single Leaf Wood Door W/Frame	3	EA	0	3	-	-
DOOR HARDWEAR SET								
76		Allowance Is Added For Door Hardware Set	12	EA	0	12	-	-

Email: info@rbcestimation.com
Call/WhatsApp: +1 737 307 6614

#	REF.	DESCRIPTION	QTY.	UNIT	WASTAGE	TOTAL QTY.	UNIT COST	TOTAL COST
09. FINISHES								
FLOORING								
FLOOR FINISHES								
77		HWD01: Existing Surface To Be Refinished	561.04	SF	0.1	618	-	-
78		HWD02: Hardwood Flooring	1096.13	SF	0.1	1206	-	-
79		ED01: Exterior Wood Decking	14.5	SF	0.1	16	-	-
80		TL01:Daltile (12"x12")	111.46	SF	0.1	123	-	-
BASE, TRIMS, TRANSITIONS								
81		B03:Hardwood base W/ -Shoe Molding	231	LF	0.1	255	-	-
82		Aluminum Flooring Transition Strip	5.51	LF	0.1	7	-	-
83		Door Trim	415	LF	0.1	457	-	-
84		Window Trim	182	LF	0.1	201	-	-
DRYWALL								
85		5/8" Mold Resistant Gypsum Board	330	SF	0.1	363	-	-
86		5/8" Gypsum Board	1140	SF	0.1	1254	-	-
87		Sealant	294	LF	0.1	324	-	-
CEILING								
88		1/2" Gypsum Board Ceiling	1114.88	SF	0.1	1227	-	-
Sum Of Sheets Size(4x8)								
Screws								
89		Tapping	1292.44	LF	0.1	1422	-	-
90		Joint Compound	137	LBS	0.1	151	-	-
WALL FINISHES								
WALL COVERINGS								
91		Bead Board Wainscoting Basic Of Design:Nantucket (1/2"-3/4") Color:White	174.93	SF	0.1	193	-	-
PAINTING								
WALL PAINT								
92		Paint @ Wall MNF:Benjamin Moore Color:Oystershell-864	5780	SF	0.1	6358	-	-
CEILING PAINT								

Email: info@rbcestimation.com

Call/WhatsApp: +1 737 307 6614

#	REF.	DESCRIPTION	QTY.	UNIT	WASTAGE	TOTAL QTY.	UNIT COST	TOTAL COST
93		PT01:Paint @ Ceiling MNF:Benjamin Moore Color:White OC-151	1756	SF	0.1	1932	-	-
94		PT01:Paint @ Wall MNF:Benjamin Moore Color:White OC-151	64.57	SF	0.1	72	-	-
95		Paint PT3@ Wall MNF:Benjamin Moore Color:Oystershell-864	417.16	SF	0.1	459	-	-
MISC. PAINT								
96		PT-05: Paint @ 1-1/2" Steel Tube Handrail MNF:Benjamin Moore Color:Universal Black 2118-10	19.1	LF	0.1	22	-	-
97		PT-05: Paint @ Steel Top Guardrail MNF:Benjamin Moore Color:Universal Black 2118-10	11.58	LF	0.1	13	-	-
98		PT02:Paint @ Crown Molding MNF:Benjamin Moore Color:White OC-151	307.95	LF	0.1	339	-	-
99		B01:Paint @ Existing Base MNF:Benjamin Moore Color:White OC-151	328.46	LF	0.1	362	-	-
100		Paint @ Hardwood base W/ -Shoe Molding MNF:Benjamin Moore Color:White OC-151	231	LF	0.1	255	-	-
101		PT02:Paint @ Board MNF:Benjamin Moore Color:White OC-151	7.08	SF	0.1	8	-	-
102		PT02:Paint @ Cabinet MNF:Benjamin Moore Color:White OC-151	21.43	LF	0.1	24	-	-
103		Wood Wainscotting Cap Trim	53.01	LF	0.1	59	-	-
104		PT02:Paint @ Wood Wainscotting Cap Trim MNF:Benjamin Moore Color:White OC-151	53.01	LF	0.1	59	-	-
105		PT02:Paint @ Door Trim MNF:Benjamin Moore Color:White OC-151	415	LF	0.1	457	-	-
106		Paint @ Door	12	EA	0	12	-	-
107		PT02:Paint @ Window Trim MNF:Benjamin Moore Color:White OC-151	297	LF	0.1	327	-	-
10. SPECIALITIES								
BATHROOM ACCESSORIES								
108		Toilet Paper Dispenser	2	EA	0	2	-	-
109		18" Grab Bar	1	EA	0	1	-	-
110		36" Grab Bar	1	EA	0	1	-	-

RBC ESTIMATION
DESIGN | ESTIMATION | MANAGEMENT

Email: info@rbcestimation.com

Call/WhatsApp: +1 737 307 6614

#	REF.	DESCRIPTION	QTY.	UNIT	WASTAGE	TOTAL QTY.	UNIT COST	TOTAL COST
111		42" Grab Bar	1	EA	0	1	-	-
112		(24"x30") Mirror	2	EA	0	2	-	-
113		Fire Extinguisher	2	EA	0	2	-	-
SHELVING								
114		1'-3" Wood Shelf W/ -L-Brackets Support	1.36	LF	0.1	2	-	-
12. FURNISHINGS								
COUNTERTOP & BACKSPLASH								
115		LM01: Plastic Laminate Countertop	2.99	SF	0.1	4	-	-
116		(2'-2" Deep) Plastic Laminate Countertop	11.42	SF	0.1	13	-	-
117		(2'-0" Deep) Plastic Laminate Vanity Countertop	5.06	SF	0.1	6	-	-
31. EARTHWORK								
GRADING								
CUT & FILL								
118		Damaged Ground To Be Repaired & Re-Seeded	464.81	SF	0.1	512	-	-
SOIL IMPORT /EXPORT								
119		Soil TO Be Export	7	CY	0.1	7.7	-	-
SITE CLEARING								
120		Site Clearing & Grubbing	1	SF	0.1	2	-	-
EXCAVATION								
121		Excavations	15	CY	0.1	16.5	-	-
122		Backfill	8	CY	0.1	8.8	-	-
32. EXTERIOR IMPROVEMENTS								
HARDSCAPE								
CONCRETE PAVEMENT & ACCESSORIES								
123		6"W Concrete Pad -Reinforced W/#4 Bar @ 12" O.C. -6" Crushed Stone	70.27	SF	0.1	78	-	-
124		8" Concrete Footing Reinforced W/ #4 Bars @ 12" O.C.	2.68	CY	0.1	2.95	-	-
125		8" Concrete Stem Wall (1'-7"H) Reinforced W/(4)#4 Hor. Bars -#4 Beant Bars @ 24" O.C.	1.4	CY	0.1	1.55	-	-
126		4"x6" Concrete Curb	0.21	CY	0.1	0.24	-	-
127		1/2" Expansion Joint	26.26	LF	0.1	29	-	-

Email: info@rbcestimation.com

Call/WhatsApp: +1 737 307 6614

#	REF.	DESCRIPTION	QTY.	UNIT	WASTAGE	TOTAL QTY.	UNIT COST	TOTAL COST
128		ADA Compliant Door Threshold	2.9	LF	0.1	4	-	-
129		4" Concrete Ramp Reinforced W/ 4x4 W2.9/W2.9 WWM Finish: Broom	147.57	SF	0.1	163	-	-
130		12" Compacted Crushed Stone Sub Base	6.68	CY	0.1	7.36	-	-
FENCES & GATE								
131		1-1/2" Tube Guard Painted Steel Guardrail 14GA (42" H) W/-1-1/2"x14GA Steel Tube Bluster @ 4" O.C.	34.67	LF	0.1	39	-	-
132		1-1/2" Tube Guard Painted Steel Handrail 14GA (36" H)	34.67	LF	0.1	39	-	-

RBC ESTIMATION
DESIGN | ESTIMATION | MANAGEMENT

RBC ESTIMATION
DESIGN | ESTIMATION | MANAGEMENT

Email: info@rbcestimation.com

Call/WhatsApp: +1 737 307 6614

GC ESTIMATE - ALTERNATE 3RD FLOOR

Project Name:	Location:	Scope of Work:	Building Type:
Sample GC 01	New York	GC	Residential

#	REF.	DESCRIPTION	QTY.	UNIT	WASTAGE	TOTAL QTY.	UNIT COST	TOTAL COST
00. PROCUREMENT & CONTRACTING REQUIREMENTS								
01. GENERAL CONDITIONS								
INDIRECT PROJECT COSTS								
12		General Liability Insurance	0	Mo	0	0	-	-
13		General Conditions (Backoffice Overhead)	0	Mo	0	0	-	-
DIRECT PROJECT COSTS								
14		Bonding Fee (If required)	1.15	Mo	0	1.15	-	-
15		Access Control (Pipe Scaffolding or Boom/Scissor Lifts)	1	Mo	0	1	-	-
16		Equipment Rental	1	Mo	0	1	-	-
17		Travel, Tools, Gas	1	Mo	0	1	-	-
18		Field Office	1	Mo	0	1	-	-
19		Temp. Facilities	1	Mo	0	1	-	-
20		Temp. Signage and Protection	1	Mo	0	1	-	-
21		Temp. Fencing	1	Mo	0	1	-	-
22		Field Superintendent/Foreman (Full Time)	1	Mo	0	1	-	-
23		Project Manager (Part Time)	1	Mo	0	1	-	-
02. DEMOLITION OF EXISTING ITEMS								
REMOVAL, DEMOLITION								
24		3" Core Drill	3	EA	0	3	-	-
25		Remove Existing Wall	249.7	SF	0.1	275	-	-
26		Remove Existing Baseboard	44.17	LF	0.1	49	-	-
27		Remove & Reinstall Crown Molding	213.53	LF	0.1	235	-	-
28		Remove & Reinstall Existing Wainscoting	4.75	SF	0.1	6	-	-
29		Remove Existing Flooring	51.36	SF	0.1	57	-	-
30		Remove Existing Door & Salvage For Future Use	3	EA	0	3	-	-
31		Provide Temporary Shoring For 10ft Wall	1	LS	0.1	2	-	-
32		Remove & Reinstall Existing Door Hardware	1	EA	0	1	-	-
33		Remove Existing Ceiling Tile System	365.86	SF	0.1	403	-	-
34		Remove Existing Plaster & Lath Ceiling	20.24	SF	0.1	23	-	-
35		Repair And Restore Existing Wood Railing	9.31	LF	0.1	11	-	-
36		Refinish Existing Wood Stairs. Replace All Broken Treads (APX. 25%)	1	LS	0.1	2	-	-
37		Patch & Repair Existing Plaster & Lath Ceiling & Prepare For Paint	400.88	SF	0.1	441	-	-

RBC ESTIMATION
DESIGN | ESTIMATION | MANAGEMENT

Email: info@rbcestimation.com

Call/WhatsApp: +1 737 307 6614

#	REF.	DESCRIPTION	QTY.	UNIT	WASTAGE	TOTAL QTY.	UNIT COST	TOTAL COST
38		Patch And Repair Existing Plaster And Lath Walls & Preparation For Paint	2840	SF	0.1	3124	-	-
06. WOOD PLASTICS & COMPOSITES								
ROUGH CARPENTRY								
BEAM, LUMBERS, HEADERS								
39		1-3/4"x9-1/2" LVL Beams	20	LF	0.1	22	-	-
WOODEN TRUSS & JOISTS								
40		1x3 Wood Studs @ 12" O.C.	536.67	LF	0.1	591	-	-
FINISHED CARPENTRY								
MILLWORK								
41		3/4" Plywood Shelf	14.22	SF	0.1	16	-	-
42		(1'-6" Deep) Base Cabinet	4.48	LF	0.1	5	-	-
43		(2'-0" Deep) Base Cabinet	9.29	LF	0.1	11	-	-
44		(1'-0" Deep) Wall Cabinet	6.45	LF	0.1	8	-	-
08. OPENINGS								
DOORS & FRAMES								
DOOR								
45		(2'-6"x7'-0") Single Leaf Wood Door W/Frame	4	EA	0	4	-	-
46		(3'-0"x6'-8") Single Leaf Wood Door W/Frame	1	EA	0	1	-	-
DOOR HARDWEAR SET								
47		Allowance Is Added For Door Hardware Set	12	EA	0	12	-	-
09. FINISHES								
FLOORING								
FLOOR FINISHES								
48		HWD01: Existing Surface To Be Refinished	870.83	SF	0.1	958	-	-
49		TL01:Daltile (12"x12")	55.22	SF	0.1	61	-	-
BASE, TRIMS, TRANSITIONS								
50		B02:Daltile Cove Base Series:Color Wheel Classic	20.26	LF	0.1	23	-	-
51		B03:Hardwood base W/ -Shoe Molding	23.19	LF	0.1	26	-	-
52		Aluminum Flooring Transition Strip	2.66	LF	0.1	3	-	-
CEILING								

Email: info@rbcestimation.com

Call/WhatsApp: +1 737 307 6614

#	REF.	DESCRIPTION	QTY.	UNIT	WASTAGE	TOTAL QTY.	UNIT COST	TOTAL COST
GYPSUM BOARD CEILING								
53		1/2" Gypsum Board Ceiling	536.67	SF	0.1	591	-	-
Sum Of Sheets Size(4x8)								
Screws								
54		Tapping	268	LF	0.1	295	-	-
55		Joint Compound	28.41	LBS	0.1	32	-	-
WALL FINISHES								
WALL COVERINGS								
56		TL02: Tile 4-1/4"x4-1/4" Color:Wheel Classic	66.79	SF	0.1	74	-	-
PAINTING								
WALL PAINT								
57		Paint @ Wall MNF:Benjamin Moore Color:Oystershell-864	2888.1	SF	0.1	3177	-	-
CEILING PAINT								
58		PT01:Paint @ Ceiling MNF:Benjamin Moore Color:White OC-151	937	SF	0.1	1031	-	-
MISC. PAINT								
59		PT02:Paint @ Crown Molding MNF:Benjamin Moore Color:White OC-151	156.42	LF	0.1	173	-	-
60		PT02:Paint @ Door Trim MNF:Benjamin Moore Color:White OC-151	394	LF	0.1	434	-	-
61		PT02:Paint @ Door	12	EA	0	12	-	-
62		PT02:Paint @ Window Trim MNF:Benjamin Moore Color:White OC-151	117	LF	0.1	129	-	-
63		B01:Paint @ Existing Base MNF:Benjamin Moore Color:White OC-151	238.81	LF	0.1	263	-	-
64		PT2:Paint @ Trim MNF:Benjamin Moore Color:White OC-151	4.77	LF	0.1	6	-	-
65		PT2:Paint @ Cabinet MNF:Benjamin Moore Color:White OC-151	42.82	SF	0.1	48	-	-
10. SPECIALITIES								

RBC ESTIMATION

Email: info@rbcestimation.com

Call/WhatsApp: +1 737 307 6614

#	REF.	DESCRIPTION	QTY.	UNIT	WASTAGE	TOTAL QTY.	UNIT COST	TOTAL COST
BATHROOM ACCESSORIES								
66		Toilet Paper Holder	1	EA	0	1	-	-
67		Robe Hoke	1	EA	0	1	-	-
68		Towel Ring	1	EA	0	1	-	-
69		Towel bar Round 18" Stainless	1	EA	0	1	-	-
70		(18-1/4"x24-1/4") Recessed Medical Cabinet	1	EA	0	1	-	-
71		Replace Missing Hardware	1	EA	0	1	-	-
72		(1'8" Deep) Replace Missing Drawers	3	EA	0	3	-	-
73		Fire Extinguisher	1	EA	0	1	-	-
SHELVING								
74		(1'-6' Deep) Cabinet Shelf	10.34	LF	0.1	12	-	-
75		(1'-4" Deep) Wood Shelf W/ Rod	7.03	LF	0.1	8	-	-
12. FURNISHINGS								
COUNTERTOP & BACKSPLASH								
76		LM01: Plastic Laminate Countertop	24.81	SF	0.1	28	-	-
77		(2'-0" Deep) Plastic Laminate Vanity Countertop	4.98	SF	0.1	6	-	-

RBC ESTIMATION
DESIGN | ESTIMATION | MANAGEMENT